VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	Gai-1854	DATE	Jun 28, 2012		
MANUFACTURER	Chrysler Group LLC (Japanese Importer : Chrysler Japan Co., Ltd.)				
DESCRIPTION OF DEFECT	Some vehicles may experience an HVAC condensate leak from the HVAC drain grommet onto the Occupant Restraint Control (ORC) module, which can lead to the illumination of the airbag warning light and a potential inadvertent airbag deployment without warning.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLES
ABA-RT38	Chrysler Grand Voyager	2008		375
			Total	375