

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic/Import Vehicles)

CAMPAIGN No.	2966	DATE	July 13,2012
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. 6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan		
DESCRIPTION OF DEFECT	Because the management of the caulking tool for the drain cook pin of the air brake tank was inappropriate, the fixation of O ring of that pin became insufficient. On that account, at the operation of drainage, some O rings come off and air leaks from that pin and then parking brake works. In this condition, as the result, the brake equipments will be overheated and lead to a fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KTT101	tank semi-trailer	2011-2012	10
KTT241S	tank semi-trailer	2012	17
KTT281	tank semi-trailer	2012	1
KL28-47LS2	tank semi-trailer	2012	1
		TOTAL	29