

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2972	DATE	JULY 13.2012
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	Some units have insufficient strength in its welded part of fan shroud, that rectifies wind of radiator fan installed radiator. Keeping operation as it is will lead the part broken and let components and radiator fan interfere each other with noise. In the worst case, it may result in running difficulties, due to detached component parts which brings radiator wreck and severe coolant leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	EG97	2011~2012	46
	EG105	2011~2012	177
			TOTAL
			223