

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI-1858	DATE	Jul 19, 2012
MANUFACTURE	Caterpillar UK LTD (Caterpillar Japan LTD)		
DESCRIPTION OF DEFECT	There is a possibility that a proper signal is not output to the transmission electronic control module from the transmission shift lever in the lever operating process due to an unstable quality of the internal diode. It may occur missing of gear speed and in the worst case, the machine might not be operated forward or/and rear direction. Therefore it is necessary to replace the transmission shift lever with good quality of internal diode.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-PED	924HZ	2010	14
		TOTAL	14

Note: This program has been reported on 28Jul2011 as GAI-1768 and 14 units are added to the target machines at this time.