

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|-----------------------|---|------|----------------|
| CAMPAIGN No. | Gai-1856 | DATE | 27, July, 2012 |
| MANUFACTURER | Kobelco Construction Machinery Co., Ltd. | | |
| DESCRIPTION OF DEFECT | <p>(1) Switches of Head Lamp and Direction Indicator on Control Panel are positioned more than 500 mm away from the center of Handle and this does not comply with Safety Standard.</p> <p>(2) Opening of Exhaust Pipe is positioned more than 30 degrees against the center line of the machine and this does not comply with Safety Standard.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------|-----------------|---------------------|-------------------|
| None | BW141AD-4 | 2006 ~ 2008 | 3 |
| | BW141AD-4AM | 2005 ~ 2010 | 8 |
| | BW151AD-4AM | 2008 | 1 |
| | BW202AD-4 | 2005 ~ 2007 | 1 |
| TOTAL | | | 13 |