

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2982	DATE	July 30, 2012
MANUFACTURER	Kitamura Manufacturing Co., Ltd.		
DESCRIPTION OF DEFECT	Due to the inappropriate lit color of lamps for checking whether compartment door locks on van-type freight trucks are locked, such red lamps, which can remain lit during travel when a lock is unlocked by a remote key, infringe on restrictions on lamps, etc. as stipulated in Article 42 of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-TZ2F24	ATLAS	2008	1
PKG-TZ2F24		2010~2011	16
SKG-SZ2F24		2012	2
KK-NKS71LAV	ELF	2001	1
KR-NKR81EAV		2003	1
PB-NKR81AN		2007	2
BDG-NPS85AN		2007~2008	4
BDG-NMS85AN		2007	1
BKG-NLR85AN		2007	1
SKG-NLR85AN		2011	3
BKG-NLR85N		2011	1
BDG-NPR85AN		2007~2009	2
BKG-NPR85AN		2008	1
BJG-NPR85AN		2008	1
BKG-NMR85AN		2008	1
NFG-NMR82AN		2008	1
BKG-NHR85AN		2011	2
BDG-NKS85AN		2007~2008	2
PKG-FSR90S2	FORWORD	2010	2
SKG-FSR90T2		2011	1
KG-FB51AB	FUSO CANTER	2002	1
PA-FG70DB		2007	1
PDG-FE70B		2007	1
PCG-FE74BV		2007	1
BJG-FE74BV		2007~2008	4
PDG-FE74BV		2007	1
PDG-FG84D		2007~2008	3
PDG-FB70B		2007	1
PDG-FE84DV		2007~2010	3
PDG-FE74DV		2008~2010	3

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-FE74BV	FUSO CANTER	2010~2011	12
SKG-FBA20		2010~2011	3
SKG-FEA50		2011	1
PDG-FK64F	FUSO FIGHTER	2009	1
KK-XZU411	TOYOTA DYNA	2003	1
PB-XZU411		2004	1
BDG-XZU368		2007	1
BDG-XZU414		2009	1
BDG-XZU308		2011	1
BJG-XKU308		2008	1
SKG-XZU775		2011	1
BKG-XZU504		2011	4
SKG-XZC600		2011	2
NBG-TRY231	DYNA	2011	1
BKG-XZU414M	HINO DUTRO	2008	1
BDG-XZU414M		2007~2008	5
BDG-XZU488M		2007	2
BDG-XZU568M		2007	7
BDG-XZU368M		2007	3
BDG-XZU508M		2007~2008	8
BKG-XZU508M		2010~2011	5
BDG-XZU308M		2007~2010	6
BDG-XZU348M		2007	1
BJG-XKU414M		2008~2010	3
BJG-XKU348M		2008	2
SDG-XZU710M		2011	1
SKG-XZU710M		2011	1
BKG-XZU344M		2011	1
SJG-XKC605M		TOTAL	143