

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3027	DATE	September. 28. 2012
MANUFACTURER	TOYOTA AUTO BODY CO.,LTD		
DESCRIPTION OF DEFECT	Due to the inappropriate selection of rear bumper which is installed as a member of rear underrun protective device on van-type trucks, width of some rear bumpers can be longer than the estimation. And, such rear underrun protective device , whose edges are located at the outside of rear wheels, infringe on restrictions on pedestrian protection side guards, etc. as stipulated in Article 18-2 of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XZC600M	HINO DUTRO	2012	25
		TOTAL	25