

VEHICLE SAFETY/POLLUTION REGALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2985	DATE	Aug. 23, 2012
MANUFACTURER	TOKO REINETU ENJINIARING CO., LTD.		
DESCRIPTION OF DEFECT	Due to the inappropriate lit color of lamps for checking whether compartment door locks on van-type freight trucks are locked, such red lamps, which can remain lit during travel when a lock is unlocked by a remote key, infringe on restrictions on lamps, etc. as stipulated in Article 42 of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KR-NKR81EAV	ELF	2006	1
KR-NKR81EAV "Kai"(modified)	ELF	2006	8
KK-NKR71EAV "Kai"(modified)	ELF	2006~2009	4
KK-NKR71LAV	ELF	2006	1
KK-NKR72LN	ELF	2006	1
KK-NPR71LV "Kai"(modified)	ELF	2006	1
KR-NPR81LV	ELF	2006	3
PA-NPR81N	ELF	2006	1
KK-NKR66EAV "Kai"(modified)	ELF	2006	1
PB-NKS81N	ELF	2006	1
PB-NPS81N	ELF	2006	1
KK-FE73CB "Kai"(modified)	FUSO CANTER	2006	2
KK-FE73EB	FUSO CANTER	2006	3
KK-FE72EEV	FUSO CANTER	2006	1
KK-FE82EEV	FUSO CANTER	2006	1
KK-FE63EEV	FUSO CANTER	2006	1
KK-FE53CEV "Kai"(modified)	FUSO CANTER	2006	2
GE-FE533BA	FUSO CANTER	2006	2

KK-FK61HK	FUSO FIGHTER	2006	1
KK-XZU410M	HINO DUTRO	2006	2
KK-XZU382M	HINO DUTRO	2006	2
VF-XKU344M	HINO DUTRO	1997	1
VF-XKU414M	HINO DUTRO	1997	1
KK-FD1JLEA	HINO RANGER	2006	1
KR-BKR81LAV "Kai"(modified)	CONDOR	2006	1
KR-BPR81AN	CONDOR	2006	1
KK-BKR71LV "Kai"(modified)	CONDOR	2006	1
KK-BKR66EAV "Kai"(modified)	CONDOR	2006	1
KK-MK252KH	CONDOR	2006	1
PB-MK37A	CONDOR	2006	2
KK-WHF5T "Kai"(modified)	TITAN	2006	2
PB-AKR81A	ATLAS	2006	1
		TOTAL	53