

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	3019	DATE	Aug. 31, 2012
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	With regard to container semi-trailers, since the bolts for fastening of both ends of crossmembers which connect both sides of the frame, are not selected properly, some of those bolts possibly become loose. Thus, the continuous use of them may make the bolted joints unsteady, and this in turn could damage the car frame, and in the worst case, cause weld cracks in material of the joints of hanger brackets which support flat springs.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KFKGG240S	Container Semi Trailer	2011-2012	11
KFKGG240S (Modified)	Container Semi Trailer	2011	3
KFKGG240W	Container Semi Trailer	2011-2012	258
KFKGG240W (Modified)	Container Semi Trailer	2011-2012	6
		Total	278