

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

|                       |  |      |             |
|-----------------------|--|------|-------------|
| CAMPAIGN No.          | GAI-1877   | DATE | Nov 6, 2012 |
| MANUFACTURER          | Volvo Truck Corporation<br>(Japanese Importer : UD Trucks Corporation )  |      |             |
| DESCRIPTION OF DEFECT | The heat shield mounted on the frame can fall down on the starter motor, due to fatigue caused by vibrations. This may cause case of fire. |      |             |

| TYPE        | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------------|-----------------|---------------------|-------------------|
| Unspecified | FH              | 2012                | 35                |
| Unspecified | FH              | 2012                | 2                 |
| QKG-H2TDA1  | FH              | 2012                | 6                 |
| QKG-H2TEA1  | FH              | 2012                | 3                 |
| LDG-H3RTF1  | FH              | 2012                | 3                 |
| - H2TEA1 -  | FH              | 2012                | 1                 |
|             |                 | TOTAL               | 50                |