

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3052	DATE	Oct.31 2012
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	A micro device on the print board of the pulse convertor which converts pulse signal of vehicle's speed to signal for the speed meter, may have insufficient anti-surge voltage ability and thus may cause damage of this particular micro device. This may cause malfunction of the vehicle's speed meter.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-KRC005	KR-25H	2011~2012	202
JDS-KRC006	KR-70H	2011~2012	74
JDS-KRC007	KRM-25H	2011~2012	15
EDR-KRC008	KRM-13H(M)	2011~2012	163
JDS-KRC010	KRM-35H	2011~2012	27
TOTAL			481