

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3042	DATE	October.18.2012
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	<p>With regard to the differential carrier on rear / front axle of heavy-duty truck with low platform, due to the inappropriate play on the spline at front side of the differential carrier, there may be excessive force toward the flange bolts which fixed the flange and spline shaft to be loaded.</p> <p>The continuous use in this condition may result in a damage of the bolt, and in the worst case, the flange will come off with propeller shaft allowing the vehicle down on the road.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-CG5YA	Quon	2010 –2011	2
LDG-CG5YL	Quon	2011	1
LDG-CG5ZA	Quon	2010 – 2011	89
LDG-CG5ZE	Quon	2010 – 2011	11
LDG-CG5ZL	Quon	2010 – 2011	14
LDG-CX5YA	Quon	2010 – 2011	10
LDG-CX5YL	Quon	2010 – 2011	12
QKG-CX5YA	Quon	2010	1
		TOTAL	140