

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3040	DATE	12, October, 2012
MANUFACTURER	Kobelco Construction Machinery Co., Ltd.		
DESCRIPTION OF DEFECT	<p>On the wiring of electric circuit, in case the clamp which fixes the main harness onto the upper frame is attached adversely due to improper assembling procedure, it may result in the interference of the main harness with the upper frame.</p> <p>This may cause the damage of the main harness because of the vibration of the vehicle, etc., and will result in the shortage so that the fuse will melt down. And it will lead to the malfunction on the parts such as the head light, side marker lamp, license plate lamp, speed meter lighting and turn signal.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-YE04	SK125W	2008~2012	79
TOTAL			79