

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3037	DATE	Oct. 11 2012
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On heavy-duty and medium-duty buses, a substandard piston might be built in the hand control valve for the parking brake. If the bus is continued to be used in this condition, it will cause a delay in parking brake operation, or the parking brake will become inoperative. In the worst case, the bus may start to roll unintentionally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
LDG-MM96FH	FUSO AERO ACE	2011～2012		7
LKG-MP35FK	FUSO AERO STAR	2010～2012		31
LKG-MP35FM		2010～2012		245
LKG-MP35FP		2010～2012		81
LKG-MP37FK		2010～2012		432
LKG-MP37FM		2010～2012		93
LKG-MS96VP		FUSO AERO ACE	2010～2012	
	FUSO AERO QUEEN	2010～2012		93
QDG-MM96FH	FUSO AERO ACE	2012～2012		2
QDG-MP35FM	FUSO AERO STAR	2012～2012		2
QDG-MP35FP		2012～2012		4
QKG-MP35FK		2012～2012		6
QKG-MP35FM		2012～2012		60
QKG-MP35FP		2012～2012		40
QKG-MP37FK		2012～2012		43
QKG-MP37FM		2012～2012		23
QRG-MS96VP		FUSO AERO ACE	2012～2012	
	FUSO AERO QUEEN	2012～2012		25
SDG-MM96FH	FUSO AERO ACE	2011～2012		28
TDG-MM96FH		2012～2012		25
SKG-MK27FH	FUSO AERO MIDI	2011～2012		16
TKG-MK27FH		2012～2012		14
LKG-AP35FK	—	2011～2011		2
LKG-AP35FM		2010～2011		20
LKG-AP35FP		2010～2011		3
LKG-AP37FK		2010～2011		24
LKG-AP37FM		2010～2010		5
LKG-AS96VP		2010～2011		17
		TOTAL		2,048