

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3035	DATE	Oct.10.2012
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain light duty trucks which equipped with an electric control manual transmission, due to the internal circuit of the motor drive unit which performs automatic control of the clutch operation is inadequate, over current can flow during the operation of the clutch motor, and the internal element of the motor drive unit can be damaged. Therefore, while a warning lamp come on, the clutch does not operate. In the worst case, the engine could stall when vehicles stop, resulting in the vehicle unable to be restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SJG-XKC605M	Hino Dutro	2011	83
SJG-XKC645M		2011	4
SJG-XKC655M		2011	14
SJG-XKU600M		2011	75
SJG-XKU600X			
SJG-XKU605M		2011	45
SJG-XKU640M		2011	13
SJG-XKU645M		2011	9
SJG-XKU650M		2011	25
SJG-XKU655M		2011	35
SJG-XKU700M		2011	9
SJG-XKU710M		2011~2012	351
SJG-XKU720M		2011	74
SJG-XKU720MKAI			
SJG-XKC605	Toyota Dyna 200	2011	13
SJG-XKC655	Toyota Dyna 300	2011	2
SJG-XKU600	Toyota Dyna 400	2011	3
SJG-XKU600A	Toyota Toyoace G25	2011	11
SJG-XKU605	Toyota Toyoace G35		
SJG-XKU645			
SJG-XKU650			
SJG-XKU655			
SJG-XKU700			
SJG-XKU710			
SJG-XKU710			
SJG-XKU710			
SJG-XKU720			
		TOTAL	805