

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3076	DATE	December.25.2012
MANUFACTURER	Niigata Transys co.,ltd .		
DESCRIPTION OF DEFECT	There is a possibility that it become impossible to drive the vehicle, by oil leaking from the hydraulic hose attached incorrectly to the bypass valve in the engine room.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM - NR2A	NR42	2012	31
		TOTAL	31