

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1886	DATE	2012/12/11
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On the G-Class (model series 463), the spot welding between the serrated rail and the airbag cover panel in the metal carrier of the instrument panel may not have been produced correctly. In the event of a vehicle crash with triggering of the front passenger airbag, it is possible that the serrated rail detaches from the airbag cover panel in the metal carrier of the instrument panel. In the worst case, the loose serrated rail might potentially enter the passenger compartment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-463270 ABA-463236	G55	2011	14
	G550	2010 ~ 2011	11
		TOTAL	25