

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	3070	DATE	December 6,2012
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	Some signal pressure in the pipe for controlling the relay emergency valve attached to a full trailer, the braking device of the rear axle, caused by improper handling of the pipe, cracks due to vibration during traveling. Therefore, continuing to use as it is, the braking force of the rear axle is reduced by air leakage, in the worst case, there is a possibility that the rear wheel brakes will not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FFB12402	—	2010~2012	81
FFC115BJ	—	2010	1
FFC115BN	—	2010	1
FFG121AJ	—	2012	1
FFS121AE	—	2010	1
FFS122AF	—	2010	1
FFB120AF	—	2011	1
NTF8C002	—	2010	2
NTF8C008	—	2010	1
NTF8C009	—	2010	1
NTF8C010	—	2011	1
		TOTAL	92