

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1901	DATE	Jan 31, 2013
MANUFACTURER	Toyo trailer. co., ltd		
DESCRIPTION OF DEFECT	The braking device of the trailer, heat treatment of improper brake camshaft, some toughness (tenacity) is missing. Therefore, if use is continued in the state as it is, while stress will concentrate on the spline portion of a brake camshaft and a brake camshaft will be damaged, there is a possibility that a brake may lose its effect.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unspecified (FAW)	Semitrailer	2011~2012	10
	Poletrailer	2006~2008	2
Unspecified (YGB)	Semitrailer	2012	3
	Fulltrailer	2012	2
TOTAL			17