

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1893	DATE	January 18, 2013
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	The tightening torque of stud bolts for the steering gearbox mounting on the engine sub frame may not be insufficient. This may eventually lead to some noise may occur the risk that the steering cannot be operated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-T75F02	PEUGEOT 308	2011	7
ABA-T7C5F02	PEUGEOT 308CC		4
ABA-T7W5F02	PEUGEOT 308SW		1
		TOTAL	12