

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 1899	Date	January 17,2013
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>Drivers may report abnormal noise from the rear of the vehicle when driving or when the service brakes are applied. This abnormal noise warns the driver that there is an issue with the vehicles braking system. Should this warning be ignored one or both of the brake caliper fixings may become sufficiently loosened to detach from the vehicle. Should both fixings become detached, the brake caliper may detach from the rear suspension knuckle and impact with the rotating road wheel leading to loss of function of a brake circuit and potential sudden deflation of the associated wheel and tire assembly. Loss of a brake circuit's function or sudden deflation of a tire will lead to an increased risk of a vehicle crash.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
CBA-LV2A	Range Rover Evoque	2012	18
Total			18