

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

| | | | |
|-----------------------|---|------|---------------|
| CAMPAIGN No. | 3 0 7 8 | DATE | Jan. 11, 2013 |
| MANUFACTURE | Caterpillar Japan LTD | | |
| DESCRIPTION OF DEFECT | There is a possibility that swash plate in steering pressure pump has inadequate hardness due to inappropriate heat treatment. The swash plate can wear excessively and piston shoes will be caught by damage on swash plate surface. Finally, the pump will lose functionality and operators cannot steer the vehicle. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------|-----------------|---------------------|-------------------|
| JDS-J6J | 962H | 2012 | 2 |
| | | TOTAL | 2 |