

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1891	DATE	2013/1/10
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	Due to an improper back stitching of an end seam, the right side windowbag could deflate more quickly than intended in the event which would deploy the right side windowbag. Consequently it may not provide sufficient occupant protection in the event the seam opens during deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-207347	E250CGI Coupe	2012	73
RBA-207359	E350 Coupe	2012	22
CBA-207373	E550 Coupe	2012	1
		TOTAL	96