

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3080	DATE	January 24 ,2013
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In the double cab truck fitted with steps of longer depth for egress/ingress improvement, the inlet of its intake duct does not fully prevent water intrusion. For this reason, water may intrude into the inlet when the truck drives through a puddle or a submerged road. This could allow water into the engine and eventually stop the engine in the worst case scenario.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
KC-FRR33D4 KC-FRR33D4V KK-FRR33D4V	FORWARD	1997-2003	41	
KK-FRR33G4V		1999-2001	5	
PA-FRR34D4		2005-2006	6	
PA-FRR34G4		2005-2007	7	
PB-FRR35D3V		2004-2006	20	
PB-FRR35G3 PB-FRR35G3V		2004-2006	15	
PB-FRR35H3V		2004-2007	26	
KK-FRS33D4J		1999-2002	4	
PB-FRS35D3J		2004-2006	8	
PB-FRS35G3J		2005-2006	8	
KC-FSR33D4 KK-FSR33D4		1997-2003	10	
KC-FSR33G4V KK-FSR33G4V		1997-2003	73	
PA-FSR34D4		2006	1	
PA-FSR34G4		2005-2006	6	
PB-FSR35D3V		2004	4	
PB-FSR35G3 PB-FSR35G3V		2004-2006	48	
KK-FSS33D4J		2000-2002	2	
KK-FSS33G4J		1999-2003	17	
PB-FSS35D3J		2005-2006	5	
PB-FSS35G3J		2004-2006	40	
			TOTAL	346