

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1898	DATE	Jan 22, 2013
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)		
DESCRIPTION OF DEFECT	Due to incorrect programming of automated manual Transmission Electronic Control Unit, the automated manual transmission may change gear to a higher position when the vehicle is being driven at very low speed and the accelerator pedal is not stepped down. This condition can cause increase of the engine RPM to compensate for insufficient engine torque, and the vehicle could accelerate unintentionally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-H2TDA1-	FH	2011	1
-H2TEA1-	FH	2011 - 2012	5
LDG-H3RTF1	FH	2011 - 2012	23
LKG-H2TDA1	FH	2010 - 2011	123
LKG-H2TEA1	FH	2010 - 2011	49
QKG-H2TDA1	FH	2011 - 2012	46
QKG-H2TEA1	FH	2011 - 2012	20
Unspecified	FH	2010 - 2012	186
LDG-M3RTF1	FM	2010 - 2011	3
LKG-M2TEA1	FM	2010	1
		TOTAL	457