

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 1 1 2	DATE	Feb.28.2013
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>On certain vehicles equipped with seating capacity of 10 and Super Long Body, due to insufficient fixing of the jig for the welding of a seat mounting bracket onto the cross member, there might be a positional deviation of the subject bracket. It has been repaired as the troubleshooting at the installation process of the seat. The fuel tank might be damaged during this repair due to inappropriate operation. If the vehicle continues to be driven in this condition, in an extreme case, there may be a fuel leak.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-KS4E26	NV350 CARAVAN	2012~2013	202
		TOTAL	202