

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1887	DATE	Feb. 25, 2013
MANUFACTURER	KTM-Sportmotorcycle AG (Japanese Importer : KTM Japan KK)		
DESCRIPTION OF DEFECT	The strengthen of the fuel hose is not enough, then fuel hose would be damaged and it would lead to fuel leakage because of fuel pressure. In worst case, the leaked fuel would be attached on the engine, and risk of fire is expected.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
250EXC-F	「250EXC-F SIX DAYS」	2012	94 units
500EXCEXA44	「500EXC」	2013	2 units
350FRFRA42	「Freeride 350」	2012	56 units
990SMVS949	「990SMR」	2012	10 units
TOTAL			162 units