

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3089	DATE	Feb. 12 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty tractors, the tightening torque of the bolts for the straps which fix the aluminum fuel tank is improper. This may cause cracks at the side of the fuel tank, leading to fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-FP54VER	「FUSO SUPER GREAT」	2010 ~ 2012	150
LKG-FP54VGR		2010 ~ 2012	55
QKG-FP54VER		2012 ~ 2012	17
QKG-FP54VGR		2010 ~ 2012	18
		TOTAL	240