

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-1890	DATE	Feb 7th , 2013
MANUFACTURE	LBCE : Link-Belt Construction Equipment Company (Japanese impoter : Hitachi Sumitomo Heavy Industries Construction Crane Co.,Ltd.)		
DESCRIPTION OF DEFECT	On the steering device, the retainer holding the pitman arm to the shaft may be loosened due to the lack of the retainer component and improper installation. In such condition the retainer could come off on steering, the pitman arm could fall off and make the vehicle inoperable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UNKNOWN	STX700-2	2011-2012	2
	STX700L-2	2010-2012	5
		TOTAL	7