

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	Gai-1905	DATE	Feb. 06. 2013
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has ascertained that at very high speeds (>160 km/h), the front side panels can work loose from the SNAPLOC fasteners at the headlight carrier.  If this happens the additional threaded fasteners can no longer reliably hold the side panels in place.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C600S	BMW C600Sport	2012	119
		TOTAL	119