

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	Gai-1904	DATE	Feb. 06. 2013
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has ascertained that the screws securing the side-stand pivot mount can work loose. Due to a process fault, the part of the frame where the side-stand pivot mount sits was not adequately cleaned.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
S1000RR	BMW S1000RR	2012	411
		TOTAL	411