VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic (Import Vehicles

CAMPAIGN No.	Gai-1903	DATE	Feb. 06. 2013	
MANUFACTURE	BMW			
	(Japanese Importer: BMW Group Japan Corp.)			
DESCRIPTION OF DEFECT	DURING LONG PERIODS OF RIDING AT SUSTAINED HIGH ENGINE RPM, VIBRATION WITHIN THE BRAKE FLUID RESERVOIR CAN CAUSE THE BRAKE FLUID TO FOAM. THIS COULD ALLOW AIR TO ENTER THE FRONT BRAKE SYSTEM WHICH COULD LEAD TO A LOSS OF FRONT BRAKING EFFICIENCY.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-K13AA	BMW K1300S	2012	72
EBL-K13AA	BMW K1300R	2012	69
		TOTAL	141