

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1917	DATE	2013/4/9
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	During a specific period of fuel filter production, there were issues with the injection molding process that could result in reduced thickness of the flange which cause the less strength against the operating fuel pressure along with highoperating temperatures. Therefore crack could be occurred in the flange, which may result in fuel smell or fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RBA-221057	S350	2011	7
CBA-221073	S550	2011	3
DBA-221171	S550L	2011	1
CBA-221173	S550L	2011	11
CBA-221174	S63L	2011	7
ABA-221179	S65L	2011	1
CBA-216373	CL550	2011	9
CBA-216374	CL63	2011	3
		TOTAL	42