

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3141	DATE	April. 11. 2013
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In certain vehicles, the inflator for passenger's airbag may be incorporating gas generating propellant which was rendered less dense than required due to inadequacies in its molding process or due to inadequate moisture absorption preventive after molding. In the event of the airbag deployment, there can be an abnormal increase in internal pressure of such an inflator, and the container of inflator could be thereby broken and scattered about, catching fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-RN1	「STREAM」	2000～2001	46,704
		2001～2002	9,630
		2002～2003	717
		2002	10
		2002	3
LA-RN2		2000～2001	6,928
		2001～2002	1,460
		2002～2003	134
		2002	1
LA-RN3		2000～2001	47,298
	2001～2002	6,575	
	2002～2003	376	
	2002	7	
	2002	3	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-RN4	「STREAM」	2001	9,446
		2001～2002	1,407
		2002～2003	58
LA-GD1	「FIT」	2001～2002	97,175
		2002～2003	2,715
		2001～2002	318
		2002～2003	3
LA-GD2	「FIT」	2001～2002	8,987
		2002～2003	262
		2001～2002	54
		2002	4
LA-GD3	「FIT」	2002～2003	2,871
		2002	3
LA-GD4	「FIT」	2002～2003	300
UA-GD1	「FIT」	2003	170
LA-ES1	「CIVIC FERIO」	2000～2001	6,567
		2001～2002	1,011
		2002～2003	75
LA-ES2	「CIVIC FERIO」	2000～2001	1,204
		2001～2002	439
		2002～2003	48
LA-ES3	「CIVIC FERIO」	2000～2001	1,109
		2001～2002	192
		2002～2003	27

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-ES3	「CIVIC FERIO」	2001	325
		2001～2002	76
		2002	24
UA-ES1		2001～2002	1,134
		2002～2003	108
ZA-ES9	「CIVIC HYBRID」	2001～2002	346
		2002～2003	61
LA-RD4	「CR-V」	2001～2002	2,322
		2002～2003	89
LA-RD5		2001～2002	8,702
		2002～2003	281
LA-GB1	「MOBILIO」	2001～2002	4,929
LA-GB2		2001～2002	1,023
UA-GB1		2003	1
LA-JD1	「THAT'S」	2002～2003	1,358
		2002～2003	370
LA-JD2		2002～2003	207
		2002～2003	94
		TOTAL	275,741