VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3153	DATE	April 23,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	is improper, t field. As a res scenario, the causing the v where the out	he unit detected as a fult, the coolant would electrical leakage wou ehicle to be the fail safeput power is restricted	tion system for the traction motor ailure has been flown out to the leak and in the worst case ld occur inside the traction motor condition (The driving condition d and the maximum speed is result in the vehicle unable to

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-U67V	「MINICAB -MiEV」	2012	1
		TOTAL	1