

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	3151	DATE	April 24 ,2013
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	In the semitrailer of shape with high center of gravity amount,when turning, an enough evaluation was not done to the axle and the wheel hub of growing of the stress that acted repeatedly.Therefore, the crack might occur in the wheel hub. As a result, the wheel hub is damaged when keeping using it with there a crack in the wheel hub, and, in the worst case, the wheel might drop out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TNF224AB	—	1994~1995	62
		TOTAL	62