

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 1908	Date	March 12,2013
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	A concern has been identified where the fuel outlet flange on certain Jaguar 2010MY 5.0L petrol engine derivative vehicles may crack. If a crack is present in the fuel outlet flange, drivers are most likely to experience fuel odour and in extreme circumstances with the vehicle static, there could be a pool of fuel underneath the rear of the vehicle, which in the presence of an ignition source could lead to a fire		

Type	Commercial name	Model year recalled	Number of vehicles
CBA-J05LB	「Jaguar XF Premium Luxury」	2010	14
CBA-J05MB	「Jaguar XFR」	2010	35
Total			49