

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 1909	Date	March 12,2013
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>1. A concern has been identified with certain Range Rover, Range Rover Sport and Discovery 4 vehicles in Japan where the proximity camera images may not be displayed. This may occur when selecting the camera home page. This can be an intermittent or permanent condition.</p> <p>2. No camera images on the display may occur when selecting reverse gear, forward gear for the first time after engine start.</p> <p>3. Customers in Japan have reported cases of heavy steering, usually after having driven at highway speeds and then returned to lower vehicles speeds such as town driving in traffic/parking and upon service inspection of the vehicle no fault can be found.</p> <p>Land Rover Range Rover and Range Rover Sport vehicles use a Servotronic steering system, where the level of Power Assisted Steering (PAS) assistance is controlled by software within the vehicles Body Control Module (BCM). The PAS system software has a back-up strategy that ensures when a fault with either the servotronic valve, which controls the level of assistance, or the relevant vehicle wiring is detected, the vehicle adopts a level of PAS assistance similar to the level that a customer would experience at normal highway speeds. This default assistance condition reduces steering assistance to ensure steering operation is suitable in all driving conditions.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
ABA-LA5N	「Discovery 4」	2010 - 2012	649
ABA-LS5N	「Range Rover Sport 5.0 V8」	2010 - 2013	577
ABA-LS5S	「Range Rover Sport SUPERCHARGED」	2010 - 2012	90
ABA-LM5N	「Range Rover Vogue 5.0 V8」	2010 - 2012	285
ABA-LM5S	「Range Rover Vogue SUPERCHARGED」	2010 - 2012	108
Total			1,709