

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1913	DATE	March 12 th 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate material of the check valve attached to brake booster vacuum line, seal-up effect may not be sufficient and engine oil mist may enter the brake booster, which may cause damage of inner diaphragm. Then brake booster air tightness may not be maintained and, in worst case, braking distance may be longer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FE48	「BMW X5 4.8i」	2007 – 2010	784
TOTAL			784