

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3123	DATE	Mar.26 2013
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	There may have interferences between the protective tube of the electric wire harness included for the valve-solenoid to correct reverse steering and a hydraulic hose equipped with the slewing table. Therefore, when you continue to use the vehicle with this condition, the harness may be damaged and it may have a short cut circuit inside, then, at worst, it may have an erratic steering operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KR205	KR-22H	1996~2003	231
KR248	KRM-25H	2003~2008	137
TOTAL			368