

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3128	DATE	Mar. 28 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>On some light-duty trucks and buses:</p> <p>(1) The clamp for the fuel return hose is missing. If the vehicle continues to be used in this condition, the fuel return hose may come off and the fuel will leak. In the worst case, it may result in fire.</p> <p>(2) The cushioning rubber which fixes the fuel return hose to the engine is improper in material and phthalate (a chemical) will elute from the rubber, which will soften the fuel return hose. Then the hose may come off from the connected orifice, causing fuel leak. In the worst case, it may result in fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FBA30	「FUSO CANTER」	2012	1
TKG-FEA50		2012	1
TKG-FEB90		2012	1
TPG-BE640G	「FUSO ROSA」	2012 ~ 2012	5
		TOTAL	8