VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1925	DATE	May 8, 2013	
MANUFACTURER	AUDI AG (Japanese Importer : Audi Japan KK)			
DESCRIPTION OF DEFECT	For 7 speed S-tronic gearbox control unit, due to improper design of plastic circuit board, electrical short circuit occurs on the power supply circuit and related fuses get cut. If the defect happens during drive, clutch will be disengaged, which leads loss of driving motive; consequently vehicle slowly loses momentum till completely stops and no further driving possible. Nevertheless, under this condition, brakes, steering, and all other related driving functions are still available to maneuver the vehicle toward safety stop. If the defect happens during stationary period, engine cannot be started or still no further driving possible even engine can be started.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-8PCAX	A3 1.4TFSI	2009 - 2010	4,328
DBA-8PCAX	A5 1.41151	2010 - 2012	4,196
ABA-8PCDA	A3 1.8T	2009 - 2012	1,548
DBA-8XCAX	A1 1.4/90kw	2011 - 2012	3,680
		TOTAL	13,752