

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-1922	DATE	May 9, 2013
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	<p>General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2006 - 2007 model year Chevrolet TrailBlazer.</p> <p>If fluid enters the driver's door module, it may cause corrosion that could result in a short in the circuit board. A short may cause the power door lock and power window switches to function intermittently or become inoperative.</p> <p>In rare cases, a short may cause overheating, which could melt components of the door module, producing odor, smoke, or a fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-T360	TrailBlazer	2006	400
GH-T360G		2007	245
GH-T370L		2006	120
GH-T370V		2006	80
		TOTAL	845