

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1930	DATE	May 20 th 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate software of the engine control unit, the evaporative gas in the fuel tank, which is absorbed by the charcoal canister, cannot be sent to intake manifold. As a result, the evaporative gas that exceeded the absorbing capacity of the charcoal canister may be released into the air, which may exceed the quality standard of fuel evaporative gas.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-YG60	BMW 760Li	2012 - 2013	10