

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1931	DATE	May 20 th 2013
MANUFACTURER	Rolls-Royce Motor Cars Limited The Drive, Westhampnett, Chichester, West Sussex, PO18 0SH, UK (Contact in Japan: Japan Representative Office, Rolls-Royce Motor Cars Limited)		
DESCRIPTION OF DEFECT	Due to inappropriate software of the engine control unit, the evaporative gas in the fuel tank, which is absorbed by the charcoal canister, cannot be sent to intake manifold. As a result, the evaporative gas that exceeded the absorbing capacity of the charcoal canister may be released into the air, which may exceed the quality standard of fuel evaporative gas.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-664S	Ghost	2012 - 2013	24
ABA-664L	Ghost EWB	2012 - 2013	17
		TOTAL	41