

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1933	DATE	May 20 th 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Manufacturing defect in gas generator compression process or excessive moisture absorption at front passenger airbag inflator may have occurred, which leads to insufficient density of the gas generator. Thus, during airbag deployment, internal pressure may increase extraordinarily that might cause inflator case rupture or fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-AT18	BMW 316ti	2002	806
GH-AU20	BMW 318ti	2002	910
GH-AY20	BMW 318i	2001 – 2002	2,407
	BMW 318Ci	2002	198
	BMW 318i Touring	2002	673
GH-AV22	BMW 320i	2002 – 2003	1,930
GH-AV25	BMW 325i	2002	535
GH-AV30	BMW 330i	2002	226
	BMW 330Ci	2002	66
	BMW 330Ci Cabriolet	2001 – 2002	130
GH-BL32	BMW M3	2002	210