

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1934	DATE	May 20 th 2013
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH+Co.KG (Japanese Importer: Nicole Racing Japan Co.,Ltd)		
DESCRIPTION OF DEFECT	Manufacturing defect in gas generator compression process or excessive moisture absorption at front passenger airbag inflator may have occurred, which leads to insufficient density of the gas generator. Thus, during airbag deployment, internal pressure may increase extraordinarily that might cause inflator case rupture or fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-3E46	ALPINA B3-3.3	2002	29
GF-3E48	ALPINA B3-3.3 4WDTouring	2002	7
GH-3E48	ALPINA B3-3.3 4WDTouring	2002	3
GH-3E50	ALPINA B3S	2002	3
	ALPINA B3S Coupe	2002	1
	ALPINA B3S Touring	2002	1
		TOTAL	44