

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1921	DATE	23 /May/2013
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	<p>Volvo Car Corporation (VCC) has decided to carry out a safety recall on a limited number of Volvo V40 vehicles (model year 2013).</p> <p>Volvo Car Corporation investigation has determined that the brake pipe for the rear wheels may be in contact with the heat shield. This may cause a chafing of the plastic cover of the brake pipe. The brake pipe wear progresses, warning light and warning messages will be displayed by brake fluid leaks. As customer' s vehicle is within the determined range of chassis numbers which may be affected by this condition, This procedure will be completed at no cost for customers and will take approximately 30 minutes. Due to service scheduling, customer' s Volvo dealers may require customer' s vehicle for a longer period of time.</p> <p>Volvo Car Corporation kindly asks customers to contact nearest authorised Volvo dealers without delay to schedule an appointment.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[V40]	2013	1.525
TOTAL			1.525