

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3154	DATE	May 15, 2013
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Siren of the emergency cars may accumulate water inside it due to its construction without any drain hole while running on a flooded road or car wash. There is a possibility that the siren won't fulfill safety regulations because of low sound pressure with continuous use of the cars.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-RE91S	KIZASHI	2012 to 2013	713
CBA-RF91S		2012 to 2013	195
DBA-YA11S	SX4	2012	162
		TOTAL	1,070