

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai—1929	DATE	May 24, 2013
MANUFACTURER	KTM-Sportmotorcycle AG  (Japanese Importer : KTM Japan KK)		
DESCRIPTION OF DEFECT	Because of improper forming of throttle grip upper housing, the throttle cable wire will be came off from the roller inside the throttle grip upper housing rarely, and the cable would be inserted between housing and roller. As a result of this, the engine running does not fall soon after throttle grip acceleration off, then in worst case, the engine continue running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
200EXC	「200EXC」	2013	18 UNITS
250EXC	「250EXC」	2012 ~ 2013	30 UNITS
250EXC	「250EXC SIX DAYS」	2011、2013	29 UNITS
		TOTAL	77 UNITS